

IDENTIFICATION

ULTRAPROBE **15,000**

15,000 IDENTIFICATION



Items included with the Ultraprobe 15,000

NOTE: UE DMS and Spectralyzer software available for download at www.uesystems.com

1. 2-Rechargeable batteries and battery charger pod
2. Extension Rods
3. Long Range Module
4. Rubber Focusing Probe
5. Stethoscope Module
6. Ultraprobe 15,000
7. Warble Tone Generator (WTB)
8. Headphones
9. Remote Magnetic Transducer (RMT)
10. WTB and UE 15,000 Charger



SAFETY: WRIST STRAP WORN ALL TIMES

15,000 IDENTIFICATION



Ultraprobe 15,000 Identification

1. 2Mb Camera with flash (Flash doubles as strobe)
2. Laser Pointer
3. IR Thermometer
4. Instrument Trigger
5. Battery Pack
6. SDCard Slot



SAFETY: WRIST STRAP WORN ALL TIMES

15,000 IDENTIFICATION



Ultraprobe 15,000 Identification



1. Touchscreen

2. Headphonejack

3. On/off Button

SAFETY: WRIST STRAP WORN ALL TIMES

15,000 IDENTIFICATION




Headphones must be worn and plugged in during inspection.



Wrist strap should be worn at all times for safety.



Press On/off button to power on.
Press dB Display icon for main display.



Touchscreen allows for quick and easy adjustments.




SAFETY: WRIST STRAP WORN ALL TIMES

15,000 IDENTIFICATION



Ultraprobe 15,000 Screen.



SAFETY: WRIST STRAP WORN ALL TIMES